

Dräger Medical Systems, Inc., Andover, MA 01810 USA

**To our customers and users of the:**

- **Infinity® Acute Care System that use Cockpits with revision index 06 or higher that contain 4GB RAM Modules.**
- **Upgrade kits that contain 4GB RAM Modules.**

**Important Safety Notice!**

**While using Infinity® Acute Care System Cockpits with 4GB RAM Modules audio or visual alarms may not annunciate on the Cockpit and Infinity Central Station due to high memory usage.**

**May 2017**

Dear Madam or Sir,

We learned that Dräger Infinity® Acute Care Systems that use the newer Cockpits with revision index 06 or higher that contain 4GB RAM modules or that received upgrade kits that contained 4GB RAM Modules may not annunciate audio or visual alarms on the Cockpit and Central Station. The M540 will still issue visual alarms. Alarm function is not affected at the M540 and Central Station when the Cockpit is disconnected.

We are not aware of any negative patient consequences arising from this issue. Our investigation revealed that this behavior is due to a failure within certain 4GB RAM Modules.

Based on the information we have, you are using at least one Infinity® Acute Care System that fits into the above criteria at your facility.

**Please use that attached list of serial numbers to identify potentially affected Cockpits. The serial number can be found on the rear side of the Cockpit. If the serial number on the cockpit is on the attached list, remove the Cockpit from use until it can be determined whether the 4GB RAM Module is among those affected. Identification can be performed by Dräger or a trained Biomed by following the instructions for “memtest 86”. The IACS can be used without the Cockpit and the M540 will function as the primary monitoring device once the Cockpit is disconnected.**

**If your Cockpit contains a 4GB RAM Module that is among the affected products, please contact your local Sales and Service representative in order for them to carry out the repair free of charge.**

Please distribute this Safety Information to all potential users within your facility.

We regret any inconvenience this may cause. We consider it a necessary preventive measure to increase patient and user safety.

If you have any further questions, please contact your local Dräger representative.

Sincerely,

Steffen Protsch

Draeger Medical Systems, Inc.

Dräger Medical Systems, Inc., Andover, MA 01810 USA

**To our customers and users that received one or more Upgrade kits  
for a Cockpit that contains 4GB RAM Modules**

**Supplement for the Important Safety Notice!**

**May 2017**

Dear Madam or Sir,

We identified that your healthcare facility received one or more 4GB RAM Module Upgrade kits for the newer version of the Cockpit. Serial Numbers of Cockpit(s) that received the 4GB RAM Module as part of an upgrade are not included on the list of Serial Numbers supplied with the Important Safety Notice although they may still be affected. To identify the potentially affected Cockpit(s) at your site we would like to ask you for your support. Please check your repair history and quarantine the latest repaired Cockpits. The quarantined devices will be checked and repaired as described in the Important Safety Notice.

We apologize for any inconvenience this action may additionally cause and appreciate your patience and cooperation.

If you have any further questions, please contact your local Dräger representative.

Sincerely,

Steffen Protsch

Draeger Medical Systems, Inc.

**Dräger Medical Systems, Inc.**

6 Tech Drive  
Andover, MA 01810 USA  
Phone: (978) 379-8000  
[www.draeger.com](http://www.draeger.com)

## Amendment to the Important Safety Notice!

May 2017

To our customers and users that received a Cockpit that contain 4GB RAM Modules

List of affected serial numbers:

Material	Material Description	Serial number
MK31501	M14.5, variant C500	401089048
MK31501	M14.5, variant C500	401089013
MK31501	M14.5, variant C500	401091016
MK31501	M14.5, variant C500	401091078
MK31501	M14.5, variant C500	401091051
MK31501	M14.5, variant C500	401091060
MK31501	M14.5, variant C500	402073009
MK31501	M14.5, variant C500	402073042
MK31501	M14.5, variant C500	402073027
MK31501	M14.5, variant C500	402073062
MK31501	M14.5, variant C500	402073004
MK31501	M14.5, variant C500	404234014
MK31501	M14.5, variant C500	404234039
MK31501	M14.5, variant C500	404234029
MK31501	M14.5, variant C500	404234040
MK31501	M14.5, variant C500	404234069
MK31501	M14.5, variant C500	404234024
MK31501	M14.5, variant C500	404234044
MK31501	M14.5, variant C500	404234032
MK31501	M14.5, variant C500	404234065
MK31501	M14.5, variant C500	404234056
MK31501	M14.5, variant C500	404234048
MK31501	M14.5, variant C500	404234036
MK31501	M14.5, variant C500	404234038
MK31501	M14.5, variant C500	404234025
MK31501	M14.5, variant C500	404234019
MK31501	M14.5, variant C500	404234013
MK31501	M14.5, variant C500	404234015
MK31501	M14.5, variant C500	374271065
MK31501	M14.5, variant C500	379843052
MK31501	M14.5, variant C500	404234018
MK31501	M14.5, variant C500	404234046
MK31501	M14.5, variant C500	401091098
MK31501	M14.5, variant C500	404234066
MK31501	M14.5, variant C500	404234062
MK31501	M14.5, variant C500	404234068
MK31501	M14.5, variant C500	404234071
MK31501	M14.5, variant C500	404234060
MK31501	M14.5, variant C500	404234079

### Dräger Medical Systems, Inc.

6 Tech Drive  
 Andover, MA 01810 USA  
 Phone: (978) 379-8000  
[www.draeger.com](http://www.draeger.com)

Material	Material Description	Serial number
MK31501	M14.5, variant C500	402073021
MK31501	M14.5, variant C500	402073067
MK31501	M14.5, variant C500	402073030
MK31501	M14.5, variant C500	376587013
MK31501	M14.5, variant C500	401089007
MK31501	M14.5, variant C500	401091035
MK31501	M14.5, variant C500	401091085
MK31501	M14.5, variant C500	401091088
MK31501	M14.5, variant C500	402073089
MK31501	M14.5, variant C500	402073063
MK31501	M14.5, variant C500	404234012
MK31501	M14.5, variant C500	401091011
MK31501	M14.5, variant C500	401091048
MK31501	M14.5, variant C500	401091055
MK31501	M14.5, variant C500	401091039
MK31501	M14.5, variant C500	401091047
MK31501	M14.5, variant C500	401091044
MK31501	M14.5, variant C500	401091038
MK31501	M14.5, variant C500	401091068
MK31501	M14.5, variant C500	401091071
MK31501	M14.5, variant C500	402073022
MK31501	M14.5, variant C500	402073024
MK31501	M14.5, variant C500	402073050
MK31501	M14.5, variant C500	402073065
MK31501	M14.5, variant C500	402073049
MK31501	M14.5, variant C500	404235077
MK31501	M14.5, variant C500	404235050
MK31501	M14.5, variant C500	404235053
MK31501	M14.5, variant C500	404235060
MK31501	M14.5, variant C500	402073056
MK31501	M14.5, variant C500	402073053
MK31501	M14.5, variant C500	402073047
MK31501	M14.5, variant C500	404234020
MK31501	M14.5, variant C500	402073043
MK31501	M14.5, variant C500	401089044
MK31501	M14.5, variant C500	401089035
MK31501	M14.5, variant C500	401089049
MK31501	M14.5, variant C500	401089039
MK31501	M14.5, variant C500	401089006
MK31501	M14.5, variant C500	401089032
MK31501	M14.5, variant C500	373821055
MK31501	M14.5, variant C500	376586021

Material	Material Description	Serial number
MK31501	M14.5, variant C500	401091003
MK31501	M14.5, variant C500	404234098
MK31501	M14.5, variant C500	404234064
MK31501	M14.5, variant C500	404234074
MK31501	M14.5, variant C500	404234067
MK31501	M14.5, variant C500	404234072
MK31501	M14.5, variant C500	404234075
MK31501	M14.5, variant C500	404234085
MK31501	M14.5, variant C500	404234078
MK31501	M14.5, variant C500	404234087
MK31501	M14.5, variant C500	404234027
MK31501	M14.5, variant C500	404234002
MK31501	M14.5, variant C500	404234003
MK31501	M14.5, variant C500	404234090
MK31501	M14.5, variant C500	404234004
MK31501	M14.5, variant C500	404234023
MK31501	M14.5, variant C500	404234028
MK31501	M14.5, variant C500	404234043
MK31501	M14.5, variant C500	404234096
MK31501	M14.5, variant C500	404234006
MK31501	M14.5, variant C500	404234009
MK31501	M14.5, variant C500	404235015
MK31501	M14.5, variant C500	404234035
MK31501	M14.5, variant C500	404234080
MK31501	M14.5, variant C500	404235016
MK31501	M14.5, variant C500	404235024
MK31501	M14.5, variant C500	404235006
MK31501	M14.5, variant C500	404235029
MK31501	M14.5, variant C500	404235018
MK31501	M14.5, variant C500	404235040
MK31501	M14.5, variant C500	404234082
MK31501	M14.5, variant C500	401089019
MK31501	M14.5, variant C500	401089009
MK31501	M14.5, variant C500	404235038
MK31501	M14.5, variant C500	404235057
MK31501	M14.5, variant C500	402073001
MK31501	M14.5, variant C500	404235061
MK31501	M14.5, variant C500	404235088
MK31501	M14.5, variant C500	404235095
MK31501	M14.5, variant C500	404235066
MK31501	M14.5, variant C500	404235054
MK31501	M14.5, variant C500	404235009

Material	Material Description	Serial number
MK31501	M14.5, variant C500	404235055
MK31501	M14.5, variant C500	404235037
MK31501	M14.5, variant C500	404235025
MK31501	M14.5, variant C500	404235004
MK31501	M14.5, variant C500	404235007
MK31501	M14.5, variant C500	404235011
MK31501	M14.5, variant C500	404235005
MK31501	M14.5, variant C500	404234084
MK31501	M14.5, variant C500	404234100
MK31501	M14.5, variant C500	404234057
MK31501	M14.5, variant C500	404234034
MK31501	M14.5, variant C500	404234091
MK31501	M14.5, variant C500	404234052
MK31501	M14.5, variant C500	404235042
MK31501	M14.5, variant C500	404235001
MK31501	M14.5, variant C500	404235028
MK31501	M14.5, variant C500	404235031
MK31501	M14.5, variant C500	404235014
MK31501	M14.5, variant C500	404235021
MK31501	M14.5, variant C500	404234001
MK31501	M14.5, variant C500	404235020
MK31501	M14.5, variant C500	404235039
MK31501	M14.5, variant C500	404235056
MK31501	M14.5, variant C500	404235030
MK31501	M14.5, variant C500	404235036
MK31501	M14.5, variant C500	404235032
MK31501	M14.5, variant C500	404235048
MK31501	M14.5, variant C500	402073008
MK31501	M14.5, variant C500	401089040
MK31501	M14.5, variant C500	402073068
MK31501	M14.5, variant C500	402073012
MK31501	M14.5, variant C500	402073057
MK31501	M14.5, variant C500	404235099
MK31501	M14.5, variant C500	404235070
MK31501	M14.5, variant C500	404235097
MK31501	M14.5, variant C500	404235008
MK31501	M14.5, variant C500	404235080
MK31501	M14.5, variant C500	404235083
MK31501	M14.5, variant C500	404235078
MK31501	M14.5, variant C500	404235065
MK31501	M14.5, variant C500	404235094
MK31501	M14.5, variant C500	404235098

Material	Material Description	Serial number
MK31501	M14.5, variant C500	404235100
MK31501	M14.5, variant C500	404235035
MK31501	M14.5, variant C500	404235068
MK31501	M14.5, variant C500	404235086
MK31501	M14.5, variant C500	404235096
MK31501	M14.5, variant C500	404235081
MK31501	M14.5, variant C500	404235051
MK31501	M14.5, variant C500	402073061
MK31501	M14.5, variant C500	402073013
MK31501	M14.5, variant C500	401091070
MK31501	M14.5, variant C500	401091086
MK31501	M14.5, variant C500	401091053
MK31501	M14.5, variant C500	401091089
MK31501	M14.5, variant C500	401091087
MK31501	M14.5, variant C500	401091049
MK31501	M14.5, variant C500	401091090
MK31501	M14.5, variant C500	401091050
MK31501	M14.5, variant C500	401091081
MK31501	M14.5, variant C500	401091002
MK31501	M14.5, variant C500	401091059
MK31501	M14.5, variant C500	401091067
MK31501	M14.5, variant C500	401091083
MK31501	M14.5, variant C500	401091007
MK31501	M14.5, variant C500	401091028
MK31501	M14.5, variant C500	401091009
MK31501	M14.5, variant C500	401091069
MK31501	M14.5, variant C500	402073079
MK31501	M14.5, variant C500	402073083
MK31501	M14.5, variant C500	402073076
MK31501	M14.5, variant C500	402073070
MK31501	M14.5, variant C500	401089043
MK31501	M14.5, variant C500	401089030
MK31501	M14.5, variant C500	401089011
MK31501	M14.5, variant C500	401089047
MK31501	M14.5, variant C500	401089002
MK31501	M14.5, variant C500	401089017
MK31501	M14.5, variant C500	401089008
MK31501	M14.5, variant C500	401091072
MK31501	M14.5, variant C500	401091001
MK31501	M14.5, variant C500	401091043
MK31501	M14.5, variant C500	401091046
MK31501	M14.5, variant C500	402073055

Material	Material Description	Serial number
MK31501	M14.5, variant C500	402073038
MK31501	M14.5, variant C500	404234094
MK31501	M14.5, variant C500	404234021
MK31501	M14.5, variant C500	401089016
MK31501	M14.5, variant C500	401089045
MK31501	M14.5, variant C500	404234053
MK31501	M14.5, variant C500	376586067
MK31501	M14.5, variant C500	402073077
MK31501	M14.5, variant C500	402073075
MK31501	M14.5, variant C500	402073081
MK31501	M14.5, variant C500	402073066
MK31501	M14.5, variant C500	402073036
MK31501	M14.5, variant C500	402073046
MK31501	M14.5, variant C500	401089050
MK31501	M14.5, variant C500	402073017
MK31501	M14.5, variant C500	404234092
MK31501	M14.5, variant C500	404234083
MK31501	M14.5, variant C500	402073080
MK31501	M14.5, variant C500	350597089
MK31501	M14.5, variant C500	404234061
MK31501	M14.5, variant C500	404234099
MK31501	M14.5, variant C500	401091034
MK31501	M14.5, variant C500	401091026
MK31501	M14.5, variant C500	401091019
MK31501	M14.5, variant C500	401091023
MK31501	M14.5, variant C500	401091020
MK31501	M14.5, variant C500	401091024
MK31501	M14.5, variant C500	401091030
MK31501	M14.5, variant C500	401091006
MK31501	M14.5, variant C500	401091032
MK31501	M14.5, variant C500	401091005
MK31501	M14.5, variant C500	401091018
MK31501	M14.5, variant C500	401091029
MK31501	M14.5, variant C500	401091022
MK31501	M14.5, variant C500	401091027
MK31501	M14.5, variant C500	401091036
MK31501	M14.5, variant C500	401091013
MK31501	M14.5, variant C500	401091017
MK31501	M14.5, variant C500	401091031
MK31501	M14.5, variant C500	401091058
MK31501	M14.5, variant C500	401091012
MK31501	M14.5, variant C500	401091091

Material	Material Description	Serial number
MK31501	M14.5, variant C500	401091040
MK31501	M14.5, variant C500	401091015
MK31501	M14.5, variant C500	401091064
MK31501	M14.5, variant C500	401091075
MK31501	M14.5, variant C500	401091073
MK31501	M14.5, variant C500	401091100
MK31501	M14.5, variant C500	401091025
MK31501	M14.5, variant C500	401091052
MK31501	M14.5, variant C500	401091097
MK31501	M14.5, variant C500	401091096
MK31501	M14.5, variant C500	401091092
MK31501	M14.5, variant C500	401091079
MK31501	M14.5, variant C500	401091080
MK31501	M14.5, variant C500	401091077
MK31501	M14.5, variant C500	401091062
MK31501	M14.5, variant C500	401091061
MK31501	M14.5, variant C500	404235047
MK31501	M14.5, variant C500	404235043
MK31501	M14.5, variant C500	404235058
MK31501	M14.5, variant C500	404235045
MK31501	M14.5, variant C500	404235044
MK31501	M14.5, variant C500	404235084
MK31501	M14.5, variant C500	404235085
MK31501	M14.5, variant C500	404235075
MK31501	M14.5, variant C500	404235091
MK31501	M14.5, variant C500	404235092
MK31501	M14.5, variant C500	404235022
MK31501	M14.5, variant C500	404235062
MK31501	M14.5, variant C500	404235071
MK31501	M14.5, variant C500	404235090
MK31501	M14.5, variant C500	404235012
MK31501	M14.5, variant C500	404235076
MK31501	M14.5, variant C500	404235074
MK31501	M14.5, variant C500	404235064
MK31501	M14.5, variant C500	404235079
MK31501	M14.5, variant C500	404235010
MK31501	M14.5, variant C500	404235041
MK31501	M14.5, variant C500	404235023
MK31501	M14.5, variant C500	404235052
MK31501	M14.5, variant C500	404235073
MK31501	M14.5, variant C500	404235017
MK31501	M14.5, variant C500	404235046

Material	Material Description	Serial number
MK31501	M14.5, variant C500	404235069
MK31501	M14.5, variant C500	404235049
MK31501	M14.5, variant C500	350599032
MK31501	M14.5, variant C500	401091065
MK31501	M14.5, variant C500	404234016
MK31501	M14.5, variant C500	404234049
MK31501	M14.5, variant C500	404234054
MK31501	M14.5, variant C500	404234081
MK31501	M14.5, variant C500	404234055
MK31501	M14.5, variant C500	404235089
MK31501	M14.5, variant C500	401091037
MK31501	M14.5, variant C500	401091082
MK31501	M14.5, variant C500	404235013
MK31501	M14.5, variant C500	404235026
MK31501	M14.5, variant C500	404235059
MK31501	M14.5, variant C500	404235087
MK31501	M14.5, variant C500	401091033
MK31501	M14.5, variant C500	401091054
MK31501	M14.5, variant C500	401091008
MK31501	M14.5, variant C500	402073088
MK31501	M14.5, variant C500	402073052
MK31501	M14.5, variant C500	402073082
MK31501	M14.5, variant C500	402073044
MK31501	M14.5, variant C500	402073037
MK31501	M14.5, variant C500	402073064
MK31501	M14.5, variant C500	402073020
MK31501	M14.5, variant C500	402073059
MK31501	M14.5, variant C500	401091021
MK31501	M14.5, variant C500	404235093
MK31501	M14.5, variant C500	401089015
MK31501	M14.5, variant C500	401089027
MK31501	M14.5, variant C500	401089041
MK31501	M14.5, variant C500	401089046
MK31501	M14.5, variant C500	401089001
MK31501	M14.5, variant C500	401089005
MK31501	M14.5, variant C500	401089010
MK31501	M14.5, variant C500	401089004
MK31501	M14.5, variant C500	401091004
MK31501	M14.5, variant C500	402073029
MK31501	M14.5, variant C500	402073058
MK31501	M14.5, variant C500	402073060
MK31501	M14.5, variant C500	402073078

Material	Material Description	Serial number
MK31501	M14.5, variant C500	402073018
MK31501	M14.5, variant C500	402073035
MK31501	M14.5, variant C500	402073086
MK31501	M14.5, variant C500	404234058
MK31501	M14.5, variant C500	404234073
MK31501	M14.5, variant C500	404234042
MK31501	M14.5, variant C500	404234045
MK31501	M14.5, variant C500	404234059
MK31501	M14.5, variant C500	404234076
MK31501	M14.5, variant C500	404234033
MK31501	M14.5, variant C500	404234041
MK31501	M14.5, variant C500	404235033
MK31501	M14.5, variant C500	401091010
MK31501	M14.5, variant C500	402073045
MK31501	M14.5, variant C500	402073051
MK31501	M14.5, variant C500	402073073
MK31501	M14.5, variant C500	402073072
MK31501	M14.5, variant C500	402073040
MK31501	M14.5, variant C500	402073039
MK31501	M14.5, variant C500	404235063
MK31501	M14.5, variant C500	404235082
MK31501	M14.5, variant C500	401089018
MK31501	M14.5, variant C500	401091066
MK31501	M14.5, variant C500	401091074
MK31501	M14.5, variant C500	401091093
MK31501	M14.5, variant C500	401091095
MK31501	M14.5, variant C500	401091056
MK31501	M14.5, variant C500	402073005
MK31501	M14.5, variant C500	402073041
MK31501	M14.5, variant C500	402073010
MK31501	M14.5, variant C500	402073034
MK31501	M14.5, variant C500	402073031
MK31501	M14.5, variant C500	402073019
MK31501	M14.5, variant C500	404234077
MK31501	M14.5, variant C500	404234031
MK31501	M14.5, variant C500	404234030
MK31501	M14.5, variant C500	404235027
MK31501	M14.5, variant C500	404235002
MK31501	M14.5, variant C500	404235019
MK31501	M14.5, variant C500	404235003
MK31501	M14.5, variant C500	404234026
MK31501	M14.5, variant C500	343415011

Material	Material Description	Serial number
MK31501	M14.5, variant C500	344038069
MK31501	M14.5, variant C500	350598048
MK31501	M14.5, variant C500	354214100
MK31501	M14.5, variant C500	401089026
MK31501	M14.5, variant C500	401089022
MK31501	M14.5, variant C500	401089020
MK31501	M14.5, variant C500	401089029
MK31501	M14.5, variant C500	401089031
MK31501	M14.5, variant C500	401089033
MK31501	M14.5, variant C500	401089025
MK31501	M14.5, variant C500	401089028
MK31501	M14.5, variant C500	401089003
MK31501	M14.5, variant C500	401089014
MK31501	M14.5, variant C500	401089023
MK31501	M14.5, variant C500	401089024
MK31501	M14.5, variant C500	401089037
MK31501	M14.5, variant C500	401089042
MK31501	M14.5, variant C500	401089012
MK31501	M14.5, variant C500	401089021
MK31501	M14.5, variant C500	401089034
MK31501	M14.5, variant C500	401091057
MK31501	M14.5, variant C500	401091014
MK31501	M14.5, variant C500	401091042
MK31501	M14.5, variant C500	401091076
MK31501	M14.5, variant C500	401091063
MK31501	M14.5, variant C500	404234070
MK31501	M14.5, variant C500	404234037
MK31501	M14.5, variant C500	404234011
MK31501	M14.5, variant C500	404234022
MK31501	M14.5, variant C500	404234063
MK31501	M14.5, variant C500	404234095
MK31501	M14.5, variant C500	404234088
MK31501	M14.5, variant C500	404234093
MK31501	M14.5, variant C500	404234010
MK31501	M14.5, variant C500	404234097
MK31501	M14.5, variant C500	350598021
MK31501	M14.5, variant C500	336996058
MK31501	M14.5, variant C500	337011078
MK31501	M14.5, variant C500	344038049
MK31501	M14.5, variant C500	350597049
MK31501	M14.5, variant C500	344040078

Material	Material Description	Serial number
MK31701	M14.7, variant C700	350603047
MK31701	M14.7, variant C700	402074009
MK31701	M14.7, variant C700	401780016
MK31701	M14.7, variant C700	344035053
MK31701	M14.7, variant C700	352066008
MK31701	M14.7, variant C700	354380009
MK31701	M14.7, variant C700	350603074
MK31701	M14.7, variant C700	401780019
MK31701	M14.7, variant C700	402074005
MK31701	M14.7, variant C700	401780006
MK31701	M14.7, variant C700	344034032
MK31701	M14.7, variant C700	350603044
MK31701	M14.7, variant C700	350603040_1
MK31701	M14.7, variant C700	354380023
MK31701	M14.7, variant C700	401780039
MK31701	M14.7, variant C700	401780038
MK31701	M14.7, variant C700	401780003
MK31701	M14.7, variant C700	401780024
MK31701	M14.7, variant C700	401780004
MK31701	M14.7, variant C700	401780001
MK31701	M14.7, variant C700	401780005
MK31701	M14.7, variant C700	401780046
MK31701	M14.7, variant C700	401780030
MK31701	M14.7, variant C700	401780012
MK31701	M14.7, variant C700	401780037
MK31701	M14.7, variant C700	401780034
MK31701	M14.7, variant C700	401780032
MK31701	M14.7, variant C700	402074020
MK31701	M14.7, variant C700	402074017
MK31701	M14.7, variant C700	402074012
MK31701	M14.7, variant C700	402074015
MK31701	M14.7, variant C700	401780023
MK31701	M14.7, variant C700	402074021
MK31701	M14.7, variant C700	402074014
MK31701	M14.7, variant C700	402074011
MK31701	M14.7, variant C700	402074016
MK31701	M14.7, variant C700	402074008
MK31701	M14.7, variant C700	350602060
MK31701	M14.7, variant C700	337018060
MK31701	M14.7, variant C700	402074018
MK31701	M14.7, variant C700	402074003
MK31701	M14.7, variant C700	401780051

Material	Material Description	Serial number
MK31701	M14.7, variant C700	354380084
MK31701	M14.7, variant C700	402074019
MK31701	M14.7, variant C700	354380097
MK31701	M14.7, variant C700	337018078
MK31701	M14.7, variant C700	350603049
MK31701	M14.7, variant C700	401780002
MK31701	M14.7, variant C700	401780025
MK31701	M14.7, variant C700	401780020
MK31701	M14.7, variant C700	401780026
MK31701	M14.7, variant C700	401780018
MK31701	M14.7, variant C700	401780022
MK31701	M14.7, variant C700	401780029
MK31701	M14.7, variant C700	401780027
MK31701	M14.7, variant C700	401780017
MK31701	M14.7, variant C700	350602014
MK31701	M14.7, variant C700	350602037
MK31701	M14.7, variant C700	374270012
MK31701	M14.7, variant C700	376595073
MK31701	M14.7, variant C700	401780053
MK31701	M14.7, variant C700	401780021
MK31701	M14.7, variant C700	401780042
MK31701	M14.7, variant C700	401780048
MK31701	M14.7, variant C700	401780054
MK31701	M14.7, variant C700	401780035
MK31701	M14.7, variant C700	401780033
MK31701	M14.7, variant C700	401780047
MK31701	M14.7, variant C700	354380073
MK31701	M14.7, variant C700	350603040
MK31701	M14.7, variant C700	354380076
MK31701	M14.7, variant C700	354380055
MK31701	M14.7, variant C700	354380059
MK31701	M14.7, variant C700	354380068
MK31701	M14.7, variant C700	354380026
MK31701	M14.7, variant C700	354380043
MK31701	M14.7, variant C700	354380062
MK31701	M14.7, variant C700	344035021
MK31701	M14.7, variant C700	350602046
MK31701	M14.7, variant C700	350603012
MK31701	M14.7, variant C700	344035033
MK31701	M14.7, variant C700	344035044
MK31701	M14.7, variant C700	354380051
MK31701	M14.7, variant C700	401780014

Material	Material Description	Serial number
MK31701	M14.7, variant C700	401780015
MK31701	M14.7, variant C700	354380021
MK31701	M14.7, variant C700	402074010
MK31701	M14.7, variant C700	401780050
MK31701	M14.7, variant C700	402074004
MK31701	M14.7, variant C700	402074007
MK31701	M14.7, variant C700	401780031
MK31701	M14.7, variant C700	402074001
MK31701	M14.7, variant C700	401780040
MK31701	M14.7, variant C700	401780044
MK31701	M14.7, variant C700	402074002
MK31701	M14.7, variant C700	401780008
MK31701	M14.7, variant C700	401780007
MK31701	M14.7, variant C700	401780010
MK31701	M14.7, variant C700	402074006
MK31701	M14.7, variant C700	401780009
MK31701	M14.7, variant C700	401780011
MK31701	M14.7, variant C700	401780036
MK31701	M14.7, variant C700	401780043
MK31701	M14.7, variant C700	401780041
MK31701	M14.7, variant C700	354380098
MK31701	M14.7, variant C700	354379026
MK31701	M14.7, variant C700	350603073
MK31701	M14.7, variant C700	354380074
MK31701	M14.7, variant C700	354380065